Fire Resistant Timber Doors Scheme

Certificate Number: IFCC 1922

Certificate

Initial Certification:	20 March 2024	**Revised:**	27 May 2026
Valid to:	19 March 2029	**Issue No:**	4

Issued by **IFC Certification Ltd** part of the Kiwa UK Group

This is to certify that

John J Higgins (Magherafelt) Ltd

Unit 4, Station Road Industrial Estate
Magherafelt
Co Derry
N. Ireland
BT45 5EY
Tel: 02879 633717

Who fabricate the following timber fire doorsets:

Halspan FD30, FD30S. Falcata FD30, FD30S.
Strebord FD30, FD30S, FD60, FD60S.
Vicaima FD30, FD30S.

has satisfied the requirements of the SDP 01 Timber Fire Door scheme v3.9. This includes the testing of products to **BS476: Part 22:1987 and BS476: Part 31:1983**, the inspection of their Factory Production Control continuing surveillance audits and testing of samples of products taken from production. The product specification and field of application to achieve up to **30 minutes integrity** are detailed on page 2 of this certificate.

David Mowatt
Head of IFC Certification /
Kiwa UK

kiwa CERTIFIED Product Scheme IFC Certification

UKAS PRODUCT CERTIFICATION 0175

Certificate is only valid if verified on the website.
Check the validity of this certificate by scanning this QR Code or visiting www.ifccertification.com/search/

KIWA
IFC Certification Ltd
Ground Floor, Suite A
Building 2,
Bear Brook Office Park
Walton Street, Aylesbury,
Bucks, HP21 7GQ

Certificate

Certificate Number: IFCC 1922 issue 4

The production of fire-resistant timber doorsets are manufactured in accordance with the assessment/ test reports referenced within the following table:

Product Description	Fire Rating	Assessment/ Test Report
Halspan Optima	FD30	PAR/10341/01
Falcata	FD30	PAR/19649/01
Strebord 44	FD30	WF380559
Strebord 54	FD30, FD60	IFCA/08038
Vicaima	FD30	FEA/F99112
Pyroplex Rigid Box Fire and Smoke Seal	Smoke	WF167785

Signed on behalf of Kiwa UK



David Mowatt
Head of IFC Certification /
Kiwa UK

The scope of the certification is limited to the details and parameters contained within these reports and all aspects of the specification and limitations defined therein must be satisfied.

It is the certificate holder's responsibility to ensure that the latest version/ revision of the above assessment reports are maintained as part of the audited FPC system.

Failure to comply with all specifications will invalidate the certification and may jeopardise the fire performance.